

Job Opening

If interested, please submit resume online at www.ontargetservices.com (click on applicable “job code”). If internet access is not available, an application or resume may be submitted by fax to (207) 588-4525 or mail to On Target Utility Services, Human Resources, 617 Water Street, Gardiner, ME 04345.

If not applying online, to be considered, submissions must include applicant name, phone contact and position specific “Code” (below).

LOCATION: On Target Utility Services – Portland, ME
POSITION: Fiber Optics Tester/Splicer
CODE: FOTS20-417
REPORTS TO: Operations Manager
SUBMISSION DEADLINE: Until position is filled

Essential Functions

- Responsible for the testing of fiber optic cable; along with displaying and interpreting results for the purpose of analyzing and documenting fiber optic links. Ability to operate the following devices:
 - OTDR (Optical Time-Domain Reflectometer) - measures end-to-end loss, point losses such as splices, connectors and fiber breaks.
 - Power Meter & Light Source - displays system loss over the fiber and both end connectors.
- Responsible for successfully joining optical fibers through the use of a fusion splicer. Attaining a low loss splice through a proficient cleave (cut) and splice is required.
- Ability to safely operate a bucket van.
- Travel extensively in and out-of-state.
- Must be available for weekend, night shifts, on call duty, emergency calls or on demand appointments as required or directed by Company representatives or answering service; responding as required and/or directed.
- Must be able to work a flexible schedule in order to meet customer demands/schedule.
- Must have valid driver’s license.
- Perform other duties as assigned.

Knowledge/Education/Skills/Experience

- Ability to work independently with little or no supervision.
- Must be deadline driven with the ability to work as required to meet client's needs.
- Strong organizational skills required.
- Detail oriented along with a high level of accuracy is required.
- Maintain professional appearance of self and vehicle/equipment
- Personal computer knowledge is desirable.
- Knowledge of GN Netttest (OTDR) and Alcoa Fujikura (Fusion Splicers) equipment is a plus.
- Maintain knowledge of technological changes through continuing education, training and trade articles.
- Two (2) year college degree or 2-4 years of related experience.
- Must be able to use all types of common hand tools and splicing tools of the trade.
- Has thorough knowledge of the Company’s operating standards, policies, directives and safety instructions pertaining to the work assignments.
- CDL (Commercial Driver’s License) desirable but not required.

Physical Requirements

- Must be able to climb utility poles and work out of an aerial lift devise.
- Must be able to lift 100 lbs. on an occasional basis and up to 50 lbs. on a frequent basis.
- Must be able to stand, walk and work on uneven ground for the full workday.
- Must be able to sit for long periods of time.
- Must have good eyesight and hearing capabilities.
- Must work outside in all types of weather conditions.